

RECEIVING INSPECTION REPORT

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080127-3

No. 11117

RECEIVED FROM

Carl . . Holmes Co.

DATE REC'D 1-31-57

P.O. NO. 1254

VENDOR PACKING SLIP NO. 9062

CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	ACCT. OR W.O. NO.	REMARKS
	322	000000	22064	1	0	00	00	02		
10	730145-00003 Model, #320312 (Union Switch) & Signal Host.						105			

RECEIVED
BYINSPECTED
BY

DATE

RECEIPTS RETURNED
ON SHIP. MEMO NO.

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST. PASADENA, CALIF.

No. 11119

RECEIVED FROM

DATE REC'D 1-31-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	ACCT. OR W.O. NO.	REMARKS
	322	000000	22039	0	0	00	00			
730145	1000 DELAY ASBLT									

RECEIVED

BY

THMC 1050

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080127-3

DATE

ON SHIP. MEMO NO.